


# Wrench, Striking Box



Number	S mm	L mm	Be-Cu g	Al-Cu g
160-17	17	108	105	95
160-19	19	117	135	125
160-22	22	127	192	185
160-24	24	138	270	250
160-26	26	146	320	295
160-27	27	150	350	320
160-28	28	154	365	330
160-30	30	163	460	420
160-32	32	177	610	555
160-34	34	192	690	630
160-36	36	208	780	710
160-38	38	215	875	805
160-40	40	222	895	815
160-41	41	225	985	902
160-42	42	229	1010	920
160-45	45	239	1150	1050
160-46	46	243	1275	1160
160-50	50	254	1545	1410
160-52	52	258	1570	1430
160-55	55	264	1720	1560
160-60	60	275	2080	1880
160-65	65	286	2440	2202
160-70	70	298	2735	2470
160-75	75	311	3190	2905
160-80	80	325	3485	3160
160-85	85	339	3990	3650
160-90	90	355	4350	3960
160-95	95	370	5046	4560
160-100	100	387	5630	5125
160-105	105	405	6250	5690
160-110	110	410	6480	5960
160-120	120	425	7405	6735
160-130	130	450	7905	7205
160-140	140	465	8105	7405