


Wrench, Striking Box



Number	S inch	L mm	Be-Cu g	Al-Cu g
161-1002	11/16	108	105	95
161-1004	3/4	117	135	125
161-1006	7/8	127	180	165
161-1008	1	146	320	290
161-1010	1-1/16	150	350	305
161-1012	1-1/8	159	385	350
161-1014	1-3/16	163	450	385
161-1016	1-1/4	177	610	515
161-1018	1-3/8	200	660	602
161-1020	1-13/32	208	780	715
161-1022	1-1/2	215	825	755
161-1024	1-5/8	225	925	845
161-1026	1-3/4	236	1120	1025
161-1028	1-13/16	243	1230	1125
161-1030	2	254	1425	1305
161-1032	2-1/16	258	1570	1435
161-1034	2-3/16	264	1632	1490
161-1036	2-13/64	266	1760	1605
161-1038	2-5/16	273	2080	1900
161-1040	2-3/8	275	2089	1910
161-1042	2-1/2	282	2189	2002
161-1044	2-9/16	286	2420	2195
161-1046	2-5/8	291	2442	2205
161-1048	2-3/4	298	2603	2355
161-1050	2-15/16	311	3050	2765
161-1052	3	314	3063	2802
161-1054	3-1/16	319	3220	2950
161-1056	3-1/8	325	3405	3075
161-1058	3-3/8	339	3990	3650
161-1060	3-9/16	355	4350	3960
161-1062	3-3/4	370	5046	4560
161-1064	3-15/16	387	5630	5125
161-1066	4-1/8	405	6250	5690