



# E

## Bar, Pinch




Number	L mm	Φ mm	B mm	Be-Cu g	Al-Cu g
236-1002	500	15	16	672	615
236-1004	500	19	20	1093	1001
236-1006	500	20	20	1148	1052
236-1008	500	23	23	1481	1355
236-1010	600	25	25	2132	1950
236-1012	800	23	23	2530	2293
236-1014	1000	30	28	5193	4752

## Bar, Pinch



Number	L mm	Φ mm	B mm	Be-Cu g	Al-Cu g
237-1002	500	15	15	738	675
237-1004	500	19	19	1150	1050
237-1006	500	20	20	1295	1185
237-1008	500	25	25	1975	1805
237-1010	500	30	30	2925	2675
237-1012	600	25	25	2380	2175
237-1014	600	30	30	3450	3155
237-1016	800	23	23	2290	2095
237-1018	800	25	25	3175	2905
237-1020	800	30	30	4490	4105
237-1022	850	30	30	4870	4455
237-1024	1000	25	25	3985	3645
237-1026	1000	28	28	4710	4305
237-1028	1000	30	30	5595	5115
237-1030	1200	25	25	4795	4385
237-1032	1200	30	30	6970	6375
237-1034	1500	30	30	8665	7925

## Bar, Pinch



Number	L mm	H mm	B mm	Be-Cu g	Al-Cu g
238-1002	600	3	52	2435	2221